



INSPECTION DATE 2026-10-22	MILEAGE 107251 km	ENGINE 3.6L 6 Cylinder	FUEL Petrol
TRANSMISSION Automatic	COLOUR Gray	VIN 1C4JJXFG9NW184289	REGIONAL SPEC American
NUMBER OF KEYS 1	SPARE TYRE Available		

Report Summary



86%

GOOD, MINOR ITEMS NOTED

OVERALL CONDITION SCORE

67	52	15
CHECKPOINTS	PASSED	FAILED

TYRES & RIMS

TYRE DETAILS

Tyre	Brand	Year	Size	Condition	Photos
Front Right	BFGoodrich	JAN 2022	315/70R17	Dry cracks	
Front Left	BFGoodrich	JAN 2022	315/70R17	Dry cracks	
Rear Right	BFGoodrich	JAN 2022	315/70R17	Dry cracks	—
Rear Left	BFGoodrich	JAN 2022	315/70R17	Dry cracks	

Rims	PASS

BRAKE AND DISC

Front Brake	PASS
Rear Brake	PASS
Hand Brake	PASS
Disc	PASS


SUSPENSION

Front Suspension	PASS
Rear Suspension	PASS
Steering system	PASS
Wheel alignment	PASS

EXTERIOR

BODY PANEL CONDITION

Original Paint — 0 | Accident Paint — 1 | Cosmetic Paint — 0 | Dent — 3 | Scratch — 27



Hood	● 1	Front Left Fender	● 4
Front Right Fender	● 2	Front Left Door	● 2 ● 1
Front Right Door	● 2	Rear Left Door	● 1
Rear Right Door	● 1	Roof	● 8 ACCIDENT
Rear Left Quarter Panel	● 5 ● 1	Trunk	● 2

Exterior scratch / Dent — FAIL

Minor scratches and dents on vehicle body.



Trim/Badges — PASS

Panels — FAIL

Fuel door missing



Front windshield — FAIL

Replaced with aftermarket unit



Rear windshield — FAIL

Replaced



Windows — FAIL

Rear left and right quarter glass replaced with aftermarket unit



INTERIOR

Dashboard	PASS
Steering Wheel	PASS
Seats	PASS
Trim	PASS
Gear lever	PASS
Doors	FAIL

Pocket sagging, scratches




Floor Mats	FAIL

Missing



Roof Lining	FAIL

Repaired, scratches, air leaking noise observed while driving from roof seals.



Sun Visor	PASS
Center Console	FAIL

Wear and tear on button



Seat Belt	PASS

Trunk

FAIL

Scratches






ELECTRICAL


Key	PASS
Electrical Functions	PASS
Power Window	PASS
Seat controls	PASS
Ignition	PASS
Central Locking	PASS
A/C	PASS
Infotainment	PASS
Camera & Parking Sensors	PASS
Horn	PASS
Wiper	PASS
Instrument Cluster	PASS
Headlight	PASS
Brake light	PASS
Fog light	PASS
Indicator light	PASS
License plate light	PASS
Cruise Control	PASS
Soft close	N/A
Console buttons	PASS
Mirror	PASS
Sunroof	N/A

ENGINE


Engine Oil Level	PASS
Level is ok	
Engine Oil Condition	FAIL
Oil is black needs to be replaced	



Engine Leaks	FAIL
Leak from rear main seal	




Bonnet holder/strut	FAIL
Trunk struts missing	



Turbo/Supercharger	N/A
Drive Belt	PASS
Hoses	FAIL
Coolant leak from coolant hose	




Radiator	PASS
Engine Mount	PASS
Coolant Condition	PASS
Engine Idle	PASS

Engine Covers	PASS
Fender Liner	PASS
Under Body	PASS
Exhaust	PASS
Rust	FAIL

Normal corrosion on under body.



Engine Condition Video

TRANSMISSION

Transmission Fluid Level	NOT INSPECTED

Sealed transmission unit with no dipstick. Transmission fluid level and condition could not be inspected, Inspection is recommended during the next scheduled service

Leaks	PASS


No leaks found

Gear Shifting	PASS
Differential	PASS
Transfer case	PASS

CHASSIS & SUBFRAME

CHASSIS, PANELS & PILLARS

PASS



No chassis, panel or pillar issues found. All visible structural areas inspected and confirmed clear.

Overview Gallery

INTERIOR

12 photos















ENGINE BAY & UNDERCARRIAGE

39 photos











































Inspector Comments

Overall, the car is in good condition. An air leakage noise was observed while driving, roof needs to be sealed properly.

Mechanically, the car has an engine oil leak from the rear main seal and two minor coolant leaks from the hoses. These issues need to be fixed.

Tyre noise observed while driving.

INSPECTION DISCLAIMER
Important limitations of this report